

Filled out by: G J Demers

Date: 04 / 30 / 2010

### Crossing Inspection Form

Railroad: <b>WACR CRL L/S</b>	Town: <b>BARNET</b>
Valuation Sheet: <b>V 43 /</b>	Valuation Stationing: <b>2643 + 55</b>
Mile Post: <b>L 54 .12</b>	GPS Coordinates: <b>N: 44 16.957</b> <b>W: 72 03.725</b>

Crossing Name: \_\_\_\_\_

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 857 - 602K

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  Planks

Flangeway  Rubber  Rail  Plank  Wheel cut  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 100 REHF      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_

857 602 K  
U.S. DEPT. OF AGR. FOREST SERVICE INVENTORY NUMBER







