

Filled out by: G J Demers

Date: 05/23/2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: RYEGATE
Valuation Sheet: V 43 / 47	Valuation Stationing: 2439 + 01
Mile Post: L 57.99	GPS Coordinates: N: 44 13.836 W: 72 03.232

Crossing Name: _____

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 857 - 609 H

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







