

Filled out by: G J Demers

Date: 01 / 02 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: RYEGATE
Valuation Sheet: V 43 / 46	Valuation Stationing: 2393 + 00
Mile Post: L 58 .87	GPS Coordinates: N: 44 13.092 W: 72 03.482

Crossing Name: CHAIR PLANT

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 857 -

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







