

Filled out by: G J Demers

Date: 01 / 03 / 2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: RYEGATE
Valuation Sheet: V 43 / 45	Valuation Stationing: 234-5 + 02
Mile Post: L 59.77	GPS Coordinates: N: 44 12.313 W: 72 03.630

Crossing Name: PAPER MILL ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 857 - 612 R

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

857 612 R

3







RAILROAD
CROSSING

857-612R

2
TRACKS

RAILROAD
CROSSING







RAILROAD
CROSSING

857-612R

2
TRACKS

X

