

Filled out by: G J Demers

Date / Time: 05/29/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <u>ROCKINGHAM</u>
Valuation Sheet: <b>V 3 / 9</b>	Valuation Stationing: <u>442 + 72</u>
Mile Post: <b>B 8.39</b>	GPS Coordinates: N: <u>43.20899</u> W: <u>72.53401</u>

Crossing Name: DIVOLLI'S

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number \_\_\_\_\_

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel  BALLAST

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 90DY      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







