

Filled out by: G J Demers

Date / Time: 06/05/13

Crossing Inspection Form

Railroad: GMRC	Town: CHESTER
Valuation Sheet: V3/13	Valuation Stationing: 660+18
Mile Post: B 12.50	GPS Coordinates: N: 45.25615 W: 72.57705

Crossing Name: SEWAGE PLANT

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 810T

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



RAILROAD
CROSSROAD

STOP





RAILROAD
CROSSING

