

Filled out by: G J Demers

Date / Time: 06/05/11

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 /	Valuation Stationing: <u>686+40</u>
Mile Post: B 12.99	GPS Coordinates: N: <u>43.26177</u> W: <u>72.58309</u>

Crossing Name: VT. ROUTE 11

Type: Public Private Farm Other _____

Location: Main Track Siding Spur Yard Other _____

AAR DOT Number 859 812 G

Signaled: Yes No Crossbucks Yes No

Road Surface: Paved Concrete Rubber Panels Gravel

Flangeway: Rubber Rail Plank Other RUBBER INTERFACE

Overall crossing condition: Good Fair Poor

Rail Size / Type 112 RE Rail Condition: Good Fair Poor

Line of Sight: Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







RAILROAD
CROSSING

WILD RIVER
INDUSTRIAL PARK
NORTH EXCAVATING, INC.
TRUCKING & LOGGING, INC.

30

