

Filled out by: G J Demers

Date / Time: 06/10/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 14	Valuation Stationing: <u>213 + 79</u>
Mile Post: B 13.52	GPS Coordinates: N: <u>43.26780</u> W: <u>72.58965</u>

Crossing Name: VT ROUTE 103

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 85A 813 N

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 112 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____