

Filled out by: G J Demers

Date / Time: 06/10/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <u>CHESTER</u>
Valuation Sheet: <b>V 3 / 14</b>	Valuation Stationing: <u>721 + 43</u>
Mile Post: <b>B 13.66</b>	GPS Coordinates: N: <u>43.26933</u> W: <u>72.59118</u>

Crossing Name: FIRST AVENUE CROSSING

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 859 814Y

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 112 RE      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







