

Filled out by: G J Demers

Date / Time: 06/11/13

Crossing Inspection Form

Railroad: GMRC	Town: CHESTER
Valuation Sheet: V3 / 15	Valuation Stationing: 753 + 78
Mile Post: B 14.28	GPS Coordinates: N: 43. 27556 W: 72. 59972

Crossing Name: CHURCH STREET

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 818 X

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 115 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







