

Filled out by: G J Demers

Date / Time: 06/11/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <b>CHESTER</b>
Valuation Sheet: <b>V3 / 15</b>	Valuation Stationing: <b>763 + 79</b>
Mile Post: <b>B 14.47</b>	GPS Coordinates: N: <b>43.27771</b> W: <b>72.60231</b>

Crossing Name: ROWE'S

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number —

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel + BALLAST

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 90DY      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







