

Filled out by: G J Demers

Date / Time: 06/18/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <u>CHESTER</u>
Valuation Sheet: <b>V 3 / 18</b>	Valuation Stationing: <u>919+71</u>
Mile Post: <b>B</b> <u>17.42</u>	GPS Coordinates: N: <u>43.31956</u> W: <u>72.60867</u>

Crossing Name: SOUTH MEADOW

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number                     

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel + BALLAST

Flangeway  Rubber  Rail  Plank  Other WHEELCUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 105 DY      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







