

Filled out by: G J Demers

Date / Time: 06/20/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CHESTER</u>
Valuation Sheet: V 3 / 20	Valuation Stationing: <u>1006 + 37</u>
Mile Post: B 19.06	GPS Coordinates: N: <u>43.34 068</u> W: <u>72.61 279</u>

Crossing Name: BALCH'S

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 059 035 N

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



RAILROAD
CROSSING

X





RAILROAD
CROSSING



