

Filled out by: G J Demers

Date / Time: 06/21/13

Crossing Inspection Form

| | |
|----------------------------------|--|
| Railroad: GMRC | Town: <u>CAVENDISH</u> |
| Valuation Sheet: V 3 / 20 | Valuation Stationing: <u>1047 + 22</u> |
| Mile Post: B 19.83 | GPS Coordinates: N: <u>43,35172</u> W: <u>72.61019</u> |

Crossing Name: ROCKY LEDGE

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number —

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel BALLAST

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







