

Filled out by: G J Demers

Date / Time: 06/21/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CAVENDISH</u>
Valuation Sheet: V 3 / 21	Valuation Stationing: <u>1092+21</u>
Mile Post: B 20.68	GPS Coordinates: N: <u>43.36350</u> W: <u>72.60645</u>

Crossing Name: DENSMORE ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 839 R

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







