

Filled out by: G J Demers

Date / Time: 06(24)13

Crossing Inspection Form

| | |
|----------------------------------|--|
| Railroad: GMRC | Town: <u>CAVENDISH</u> |
| Valuation Sheet: V 3 / 22 | Valuation Stationing: <u>1146+38</u> |
| Mile Post: B 21.71 | GPS Coordinates: N: <u>43.37624</u> W: <u>72.59909</u> |

Crossing Name: LIME KILN

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number —

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel + BALLAST

Flangeway Rubber Rail Plank Other WIRE CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







