

Filled out by: **G J Demers**

Date / Time: 06/25/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CAVENDISH</u>
Valuation Sheet: V 3 / 22	Valuation Stationing: <u>1159 + 51</u>
Mile Post: B 21.96	GPS Coordinates: N: <u>43.37870</u> W: <u>72.60255</u>

Crossing Name: CAVENDISH ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 844 M

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







