

Filled out by: G J Demers

Date / Time: 07/08/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CAVENDISH</u>
Valuation Sheet: V 3 / 24	Valuation Stationing: <u>1248 + 68</u>
Mile Post: B 23.64	GPS Coordinates: N: <u>43.38215</u> W: <u>72.63477</u>

Crossing Name: MOUNTAIN VIEW

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 847 H

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel + BALLAST

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 130 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







