

UPDATE

Filled out by: **G J Demers**

Date / Time: 07/09/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <b>CAVENDISH</b>
Valuation Sheet: <b>V 3 /</b>	Valuation Stationing: <b>1282+17</b>
Mile Post: <b>B 24.28</b>	GPS Coordinates: N: <b>43.38241</b> W: <b>72.64674</b>

Crossing Name: VT ROUTE 103

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location:  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 859 849 W

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 105      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_





SOUTH  
HIGHWAY  
103



STATE ROUTE 103





RAIL CROSSING

NORTH  
108  
EAST  
131