

Filled out by: G J Demers

Date / Time: 07/11/13

### Crossing Inspection Form

Railroad: <b>GMRC</b>	Town: <u>LUDLOW</u>
Valuation Sheet: <b>V3/26</b>	Valuation Stationing: <u>1339+18</u>
Mile Post: <b>B 25.36</b>	GPS Coordinates: N: <u>43,38580</u> W: <u>72,86636</u>

Crossing Name: INDUSTRIAL

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number \_\_\_\_\_

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other WHEEL CUT

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 105      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_







