

Filled out by: G J Demers

Date / Time: 07/16/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V 3 / 27	Valuation Stationing: <u>1379 + 97</u>
Mile Post: B 26.13	GPS Coordinates: N: <u>43,38926</u> W: <u>72.68066</u>

Crossing Name: SOAPSTONE ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 855 A

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 115 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







