

Filled out by: G J Demers

Date / Time: 07/18/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V 3 / 28	Valuation Stationing: <u>1459 + 81</u>
Mile Post: B 27.64	GPS Coordinates: N: <u>43.39552</u> W: <u>72.70733</u>

Crossing Name: WEST HILL ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 859 C

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 112 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____



RAILROAD
CROSSING







RAILROAD
CROSSING

CROSS ROAD

