

UPDATE

Filled out by: **G J Demers**

Date / Time: 08/21/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V3 / 32	Valuation Stationing: <u>1638 + 36</u>
Mile Post: B 31.02	GPS Coordinates: N: <u>43,43447</u> W: <u>72.73266</u>

Crossing Name: Kelly's

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number _____

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels ~~Gravel~~ ^{BALAST}

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







