

UPDATE

Filled out by: G J Demers

Date / Time: 08/26/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>Mt. Holly</u>
Valuation Sheet: V 3 / 33	Valuation Stationing: <u>1724 + 99</u>
Mile Post: B 32.67	GPS Coordinates: N: <u>43,43222</u> W: <u>72,76361</u>

Crossing Name: STATION ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 8657

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

HELDVILLE TRAILHEAD PARKING







