

Filled out by: G J Demers

Date / Time: 08/26/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>MT. HOLLY</u>
Valuation Sheet: V 3 / 33	Valuation Stationing: <u>1730 + 18</u>
Mile Post: B 32.76	GPS Coordinates: N: <u>43.43208</u> W: <u>72.76550</u>

Crossing Name: HEADVILLE ROAD

Type: Public Private Farm Other _____

Location: Main Track Siding Spur Yard Other _____

AAR DOT Number 059 866 M

Signaled: Yes No Crossbucks: Yes No

Road Surface: Paved Concrete Rubber Panels Gravel

Flangeway: Rubber Rail Plank Other WHEEL CUT

Overall crossing condition: Good Fair Poor

Rail Size / Type 105 DY Rail Condition: Good Fair Poor

Line of Sight: Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







RAIL CROSSING
CROSS ROAD



