

Filled out by: G J Demers

Date / Time: 08/27/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>Mt. Holly</u>
Valuation Sheet: V 3 / 35	Valuation Stationing: <u>1801+05</u>
Mile Post: B 34.10	GPS Coordinates: N: <u>43.44693</u> W: <u>72.78114</u>

Crossing Name: SUMMIT ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 867 U

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







