

Filled out by: **G J Demers**

Date / Time: 09/04/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>MT. HOLLY</u>
Valuation Sheet: V 3 / 37	Valuation Stationing: <u>1927 + 53</u>
Mile Post: B 36.50	GPS Coordinates: N: <u>43.44780</u> W: <u>72.82142</u>

Crossing Name: SNOWMOBILE

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number _____

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







