

Filled out by: G J Demers

Date / Time: 09/04/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>MT. HOLY</u>
Valuation Sheet: V 3 / 37	Valuation Stationing: <u>1938 + 93</u>
Mile Post: B 36.72	GPS Coordinates: N: <u>43, 44718</u> W: <u>72, 82562</u>

Crossing Name: BELMONT ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 872 R

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 115 RE Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







