

Filled out by: **G J Demers**

Date / Time: 09/06/11

Crossing Inspection Form

Railroad: GMRC	Town: <u>MT. HOLLY</u>
Valuation Sheet: V 3 / 39	Valuation Stationing: <u>2011 + 27</u>
Mile Post: B 38.09	GPS Coordinates: N: <u>43,44728</u> W: <u>72.85232</u>

Crossing Name: BOWLSVILLE

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 859 875 L

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







