

Filled out by: **G J Demers**

Date / Time: 09/20/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>SAREWSBURY</u>
Valuation Sheet: V 3 / 44	Valuation Stationing: <u>2316 + 41</u>
Mile Post: B 43.86	GPS Coordinates: N: <u>43.50414</u> W: <u>72.89790</u>

Crossing Name: KELLY FARM

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number _____

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____







