

Filled out by: G J Demers

Date / Time: 09/25/13

Crossing Inspection Form

Railroad: GMRC	Town: <u>CLARENDON</u>
Valuation Sheet: V 3 / 47	Valuation Stationing: <u>2439 + 31</u>
Mile Post: B <u>46.19</u>	GPS Coordinates: N: <u>43.52545</u> W: <u>72.93182</u>

Crossing Name: RAILROAD DRIVE

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number —

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel

Flangeway Rubber Rail Plank Other WHEEL CUT

Overall crossing condition Good Fair Poor

Rail Size / Type 105 DY Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____









MPBAG-20