

Filled out by: G J Demers

Date / Time: 10/01/13

### Crossing Inspection Form

|                                  |                                                |
|----------------------------------|------------------------------------------------|
| Railroad: <b>GMRC</b>            | Town: CLARENDON                                |
| Valuation Sheet: <b>V 3 / 50</b> | Valuation Stationing:<br>2614 + 12             |
| Mile Post: <b>B 49.50</b>        | GPS Coordinates:<br>N: 43.56747<br>W: 72.95843 |

Crossing Name: NORTH SHREWSBURY ROAD

Type:  Public  Private  Farm  Other \_\_\_\_\_

Location  Main Track  Siding  Spur  Yard  Other \_\_\_\_\_

AAR DOT Number 859 898 T

Signaled  Yes  No      Crossbucks  Yes  No

Road Surface  Paved  Concrete  Rubber Panels  Gravel

Flangeway  Rubber  Rail  Plank  Other \_\_\_\_\_

Overall crossing condition  Good  Fair  Poor

Rail Size / Type 105 DY      Rail Condition  Good  Fair  Poor

Line of Sight  Good  Fair  Poor

Number of Photos Taken 4

Remedial Action (if any) \_\_\_\_\_



RAIL  
CROSSING







