

Filled out by: G J Demers

Date: 04/28/2010

Crossing Inspection Form

Railroad: WACR CRL L/S	Town: RYEGATE
Valuation Sheet: V 43 / 42	Valuation Stationing: 2174 + 02
Mile Post: L 63.01	GPS Coordinates: N: 44 09.773 W: 72 02.936

Crossing Name: _____

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 862 - 978 P

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 100 REHF Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____

862 978 P



63







