

Filled out by: G J Demers

Date: 07 / 16 / 2014

Crossing Inspection Form

Railroad: WACR M&BD	Town: <u>BARRI</u>
Valuation Sheet: Page <u>16</u> of <u>18</u>	Valuation Stationing: <u>561 + 42</u>
Mile Post: M <u>10.63</u>	GPS Coordinates: N: <u>44 10 23</u> W: <u>72 29 10</u>

Crossing Name: LAWSON ROAD

Type: Public Private Farm Other _____

Location Main Track Siding Spur Yard Other _____

AAR DOT Number 900 - 589 P

Signaled Yes No Crossbucks Yes No

Road Surface Paved Concrete Rubber Panels Gravel Planks

Flangeway Rubber Rail Plank Wheel cut Other _____

Overall crossing condition Good Fair Poor

Rail Size / Type 85 Rail Condition Good Fair Poor

Line of Sight Good Fair Poor

Number of Photos Taken 4

Remedial Action (if any) _____