

UPDATE

Filled out by: G J Demers

Date / Time: 05/06/13

Switch Inspection Form

Railroad: GMRC	Town: ROCKINGHAM
Valuation Sheet: V3/1	Valuation Stationing: 2 + 47.7
Mile Post: B 0.05	GPS Coordinates: N: 43.13637 W: 72.44136

Switch Name: PLATFORM

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 90 DY Condition Good Fair Poor

Turnout Type #9 Right Hand Left Hand Equilateral

Switch Point Length 16'6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 12 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



