

Filled out by: G J Demers

Date / Time: 07/15/13

Switch Inspection Form

Railroad: GMRC	Town: LUDLOW
Valuation Sheet: V 3 / 26	Valuation Stationing: 1335 + 62
Mile Post: B 25.29	GPS Coordinates: N: 43.38579 W: 72.66507

Switch Name: BULK

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type # 10 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 9 FT 9 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other SELF GUARDED FROG

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



