

Filled out by: G J Demers

Date / Time: 07/17/13

### Switch Inspection Form

Railroad: <b>GMRC</b>	Town: <u>LUDLOW</u>
Valuation Sheet: <b>V 3 / 27</b>	Valuation Stationing: <u>1417+18</u>
Mile Post: <b>B 26.84</b>	GPS Coordinates: N: <u>43.39408</u> W: <u>72.69212</u>

Switch Name: EAST PASSING TRACK SWITCH

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 105 DT Condition  Good  Fair  Poor

Turnout Type #9  Right Hand  Left Hand  Equilateral

Switch Point Length 16' 6" Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 18' FT 6 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



