

Filled out by: G J Demers

Date / Time: 07/12/13

Switch Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V 3 / 28	Valuation Stationing: <u>1430 + 26.9</u>
Mile Post: B 27.08	GPS Coordinates: N: <u>43.39367</u> W: <u>72.62703</u>

Switch Name: EAST BACK TRACK SWITCH

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type #10 Right Hand Left Hand Equilateral

Switch Point Length 16'6" Tie Condition Good Fair Poor

Frog Type Rigid Solid Manganese Spring Other _____

Frog Length 18 FT 6 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



