

Filled out by: G J Demers

Date / Time: 07/18/13

Switch Inspection Form

| | |
|----------------------------------|--|
| Railroad: GMRC | Town: <u>LUDLOW</u> |
| Valuation Sheet: V 3 / 28 | Valuation Stationing: <u>1431 + 28</u> |
| Mile Post: B 27.10 | GPS Coordinates: N: <u>43 . 39369</u> W: <u>72 . 69735</u> |

Switch Name: OIL TRACK

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 90 Condition Good Fair Poor

Turnout Type #9 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 12 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



