

Filled out by: G J Demers

Date / Time: 07 | 10 | 13

Switch Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: <u>V 3 / 28</u>	Valuation Stationing: <u>1439 + 27</u>
Mile Post: B <u>27.25</u>	GPS Coordinates: N: <u>43.39366</u> W: <u>72.70036</u>

Switch Name: WEST PASSING TRACK

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type # 9 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 18 FT 6 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____