

Filled out by: G J Demers

Date / Time: 07/18/13

Switch Inspection Form

Railroad: GMRC	Town: <u>LUDLOW</u>
Valuation Sheet: V 3 / 28	Valuation Stationing: <u>1440 + 37.1</u>
Mile Post: B 27.27	GPS Coordinates: N: <u>43.39371</u> W: <u>72.70078</u>

Switch Name: WEST BACK TRACK

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type #9 Right Hand Left Hand Equilateral

Switch Point Length 16'6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 17 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



