

Filled out by: G J Demers

Date / Time: 09/05/13

Switch Inspection Form

Railroad: GMRC	Town: <u>Mt. Holly</u>
Valuation Sheet: V 3 / 37	Valuation Stationing: <u>1942 + 93.6</u>
Mile Post: B 36.79	GPS Coordinates: N: <u>43.44693</u> W: <u>72.82719</u>

Switch Name: Mt. Holly Spur

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 DY Condition Good Fair Poor

Turnout Type #10 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 18 FT 7 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



