

UPDATE

Filled out by: G J Demers

Date / Time: 10/01/13

Switch Inspection Form

Railroad: GMRC	Town: <u>CLARENDON</u>
Valuation Sheet: V 3 / 50	Valuation Stationing: <u>2614 + 78</u>
Mile Post: B 49.51	GPS Coordinates: N: <u>43.56768</u> W: <u>72.95839</u>

Switch Name: EAST CARRARA'S

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 90 Condition Good Fair Poor

Turnout Type #9 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Rigid Solid Manganese Spring Other _____

Frog Length 12 FT 0 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other _____

Guardrail Type Bolted rail cast Other _____
MAIN TRACK SIDING

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



