

Filled out by: G J Demers

Date / Time: 10/02/13

Switch Inspection Form

Railroad: GMRC	Town: RUTLAND
Valuation Sheet: V 3 / 51	Valuation Stationing: 2683 + 13
Mile Post: B 50.81	GPS Coordinates: N: 43.58617 W: 72.96173

Switch Name: QUALITAD

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type #7 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 14 FT 3 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



