

Filled out by: G J Demers

Date / Time: 10/03/13

### Switch Inspection Form

Railroad: <b>GMRC</b>	Town: <b>RUTLAND</b>
Valuation Sheet: <b>V 3 / 52</b>	Valuation Stationing: <b>2730 + 84</b>
Mile Post: <b>B 51.72</b>	GPS Coordinates: N: <b>43.59731</b> W: <b>72.97043</b>

Switch Name: EAST #5

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 115 Condition  Good  Fair  Poor

Turnout Type <sup>FROG</sup> MISSING  Right Hand  Left Hand  Equilateral

Switch Point Length 16' 6" Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other REMOVED

Frog Length 18' FT 8" IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_

✓ SWITCH IS COPIED AND CLAMPED ✓



