

Filled out by: G J Demers

Date / Time: 10/03/13

Switch Inspection Form

Railroad: GMRC	Town: <u>RUTLAND</u>
Valuation Sheet: V 3 / 52	Valuation Stationing: <u>2731+96</u>
Mile Post: B 51.74	GPS Coordinates: N: <u>43.59760</u> W: <u>72.97072</u>

Switch Name: EAST NEW LONG

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 115 Condition Good Fair Poor

Turnout Type FROG MISSING Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other REMOVED

Frog Length 10 FT 8 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____

* SWITCH IS SPIKED *



