

Filled out by: G J Demers

Date / Time: 10/03/13

Switch Inspection Form

| | |
|----------------------------------|--|
| Railroad: GMRC | Town: <u>RUTLAND</u> |
| Valuation Sheet: V 3 / 53 | Valuation Stationing: <u>2754 + 86.8</u> |
| Mile Post: B 52.17 | GPS Coordinates: N: <u>43.60241</u> W: <u>72.97632</u> |

Switch Name: WEST # 5 (Below Fous Main)

Type: Main Track Siding Spur Yard Private Other _____

Rail Size / Type 105 Condition Good Fair Poor

Turnout Type # 10 Right Hand Left Hand Equilateral

Switch Point Length 16' 6" Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 18 FT 6 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other _____

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



