

Filled out by: G J Demers

Date / Time: 10/03/13

### Switch Inspection Form

Railroad: <b>GMRC</b>	Town: <u>RUTLAND</u>
Valuation Sheet: <b>V 3 / 53</b>	Valuation Stationing: <u>2755 + 79</u>
Mile Post: <b>B 52.19</b>	GPS Coordinates: N: <u>43.60253</u> W: <u>72.97649</u>

Switch Name: WEST NEW LONG

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 105 Condition  Good  Fair  Poor

Turnout Type #9  Right Hand  Left Hand  Equilateral

Switch Point Length 16'6" Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length 17 FT 3 IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_



