

Filled out by: G.J.DEMERS

Date: 09 / 28 / 2011

### Switch Inspection Form

Railroad: <b>WACR CRL B/S</b>	Town: <b>NEWBURY</b>
Valuation Sheet: <b>V 43 / 41</b>	Valuation Stationing: <b>2142 + 51</b>
Mile Post: <b>D 0.32</b>	GPS Coordinates: N: <b>44 09.300</b> W: <b>72 02.672</b>

Switch Name: NORTH WYE (REMOVED) 05/01/12

Type:  Main Track  Siding  Spur  Yard  Private  Other \_\_\_\_\_

Rail Size / Type 100 NH Condition  Good  Fair  Poor

Turnout Type \_\_\_\_\_  Right Hand  Left Hand  Equilateral

Switch Point Length \_\_\_\_\_ FT \_\_\_\_\_ IN Tie Condition  Good  Fair  Poor

Frog Type  Ridgid  Solid Manganese  Spring  Other \_\_\_\_\_

Frog Length \_\_\_\_\_ FT \_\_\_\_\_ IN Condition  Good  Fair  Poor

Switch Stand  High  Intermediate  Ground  Ergonomic  Other

Guardrail Type  Bolted rail  cast  Other \_\_\_\_\_

Signaled  Yes  No Security  Switch Lock  Keeper

Number of Photos Taken 2

Remedial Action (if any) \_\_\_\_\_













