

Filled out by: G.J.DEMERS

Date: 09 / 28 / 2011

Switch Inspection Form

Railroad: WACR CRL B/S	Town: NEWBURY
Valuation Sheet: V 43 / 41	Valuation Stationing: +
Mile Post: D .	GPS Coordinates: N: 44 09.257 W: 72 02.549

Switch Name: WYE SPUR

Type: Main Track Siding Spur Yard Private Other WYE

Rail Size / Type 100 NH Condition Good Fair Poor

Turnout Type #10 Right Hand Left Hand Equilateral

Switch Point Length 15 FT 0 IN Tie Condition Good Fair Poor

Frog Type Ridgid Solid Manganese Spring Other _____

Frog Length 9 FT 4 IN Condition Good Fair Poor

Switch Stand High Intermediate Ground Ergonomic Other

Guardrail Type Bolted rail cast Other SELF GUARDED FROG

Signaled Yes No Security Switch Lock Keeper

Number of Photos Taken 2

Remedial Action (if any) _____



